

Using Client : LMS to debugging

The zoom debugging command is as follows:

Call 100--- Reset ( after reset, adjust focus, to make pictures clear)

Call 111 222--- Automatic debugging.

